


### **Calibration and Recalibration of BMT Ozone Monitors**

The OZONE MONITOR BMT 930, and the OZONE MONITOR BMT 932, do not need recalibration as long as no failures are displayed. The life expectancy of the UV lamp is between five and ten years. The instrument will provide a LAMP LOW warning several months before the UV lamp has to be replaced.



Dr.-Ing. Franz Wallner, VDI, VDE, IOA  
President, BMT MESSTECHNIK GMBH