

Calibration and Recalibration of BMT Ozone Photometers

The OZONE ANALYZER BMT 964 does not need recalibration as long as no failures are displayed. The life expectancy of the UV lamp is between five and ten years. The analyser will provide a LAMP LOW warning several months before the UV lamp has to be replaced. Replacement of the UV lamp always has to be combined with an in-works recalibration of the instrument.



Dr.-Ing. Franz Wallner, VDI, VDE, IOA
President, BMT MESSTECHNIK GMBH