

**Calibration and Recalibration of BMT Ozone Photometers**

The OZONE ANALYZER BMT 965 does not need recalibration as long as no failures are displayed. The life expectancy of the UV lamp is between five and ten years. The analyser will provide a LAMP LOW warning several months before the UV lamp has to be replaced.



Dr.-Ing. Franz Wallner, VDI, VDE, IOA  
President, BMT MESSTECHNIK GMBH